

# Bolsas para envasado al vacío



## Bolsas 90 micras

Mod. bolsas	Medidas	Unid./Caja
B1420	14 x 20 cm	1000
B1520	15 x 20 cm	1000
B1525	15 x 25 cm	1000
B1725	17,5 x 25 cm	1000
B2030	20 x 30 cm	1000
B2040	20 x 40 cm	1000
B2135	21 x 35 cm	1000
B2530	25 x 30 cm	1000
B2535	25 x 35 cm	1000
B2540	25 x 40 cm	1000
B3040	30 x 40 cm	1000
B3550	35 x 50 cm	500

## Bolsas 145 micras

Mod. bolsas	Medidas	Unid./Caja
B2030-145	20 x 30 cm	1000
B2535-145	25 x 35 cm	1000
B3140-145	31 x 40 cm	1000
B3550-145	35 x 50 cm	500

## Bolsas cocción

Mod. bolsas	Medidas	Unid./Caja
B1627-T	16 x 30 cm	1000
B2030-T	20 x 30 cm	1000
B3040-T	30 x 40 cm	1000
B3550-T	35 x 50 cm	500

## Parches bolsas vacío cocción

Modelo	Medidas	Unid./Caja
Parche (sonda corazón)	2 metros	1



## Bolsas retráctiles 60 micras

Mod. bolsas	Medidas (cm)	Unid./Caja
B1520-R	15 x 20	1000
B2030-R	20 x 30	1000
B2535-R	25 x 35	1000
B3040-R	30 x 40	1000